



## A Notice for our Consumers

Hooli Inc. has received reports of a handful of incidents that involve the overheating and minor combustion of HooliPhones.

While the number of incidents is relatively small in comparison to the amount of HooliPhones around the world, Hooli engineers are investigating the underlying cause of these incidents. These Actions will include a full assessment of our processes, additional software and hardware testing, and complete analysis of any HooliPhones associated with the incidents.

Hooli is suggesting that HooliPhone owners power down their devices at the first sign of overheating. This also includes potentially limiting HooliPhone usage to only basic operations, and not using taxing applications like HooliVR or any video streaming services. Device owners should also not leave HooliPhones unattended while charging, or near small children and/or infants.

We ask that HooliPhone owners monitor the Hooli website for updates as we move forward with our investigation.

We appreciate your patience, and we want to ensure our valued consumers that their safety is our utmost priority.